


●形G79-□□C-□MN

CN1	CN2	CN3
1A	4	—
1B	2	—
2A	—	4
2B	—	2
3A	NC	
3B		
4A		
4B		
5A	5	—
5B	—	5
6A	7	—
6B	—	7
7A	9	—
7B	—	9
8A	11	—
8B	—	11
9A	13	—
9B	—	13
10A	15	—
10B	—	15
11A	17	—
11B	—	17
12A	19	—
12B	—	19
13A	6	—
13B	—	6
14A	8	—
14B	—	8
15A	10	—
15B	—	10
16A	12	—
16B	—	12
17A	14	—
17B	—	14
18A	16	—
18B	—	16
19A	18	—
19B	—	18
20A	20	—
20B	—	20

●形G79-I□C-□MN

CN1	CN2	CN3
1A	NC	
1B	—	3
2A	NC	
2B	4	—
3A	NC	
3B		
4A		
4B		
5A	5	—
5B	—	5
6A	7	—
6B	—	7
7A	9	—
7B	—	9
8A	11	—
8B	—	11
9A	13	—
9B	—	13
10A	15	—
10B	—	15
11A	17	—
11B	—	17
12A	19	—
12B	—	19
13A	6	—
13B	—	6
14A	8	—
14B	—	8
15A	10	—
15B	—	10
16A	12	—
16B	—	12
17A	14	—
17B	—	14
18A	16	—
18B	—	16
19A	18	—
19B	—	18
20A	20	—
20B	—	20



コネクタピン配置図
(コネクタかん合面より)

